

S2PL

Friday 07/19/13 - A 1 year warranty walk through took place on the S2 alignment.

In attendance: Tom McBroom - CSU, Dennis Auge and Kerry Inman - MWH, Jeff Riddle and Joe Graham – Garney Construction.

The walk through started at the north end of the project and continued to the south end of the work limit, with the following findings agreed upon by the group to be address by the contractor:

- Blow off #6: Fill Void under MH lid/ Straighten bollard (Picture #1 and #2)
- CARV #4: Compaction needed around vent pipe (Picture #3)
- CARV #2: Install pipe marker (Picture #4)
- Rebar debris North of Industrial- Completed on 07/19/13
- Blow off #1: Install valve stem to isolation valve. Hand tamp around bollards. Add 2 loads of material on the surface of the trench line where settling has occurred (Picture #5, #6, and #7)





BO #6

Fill Void under MH Lid
Straighten Ballard

CARV #4

compact around vent pipe

CARV #2

Install pipeline marker

Rebar Piece North of Industrial 200'

BO #1

Install valve stem to isolation valve
Hand tamp around Ballards
Couple loads of fill 100' South of BO #1



2013/7/19

CIMG1629 Pic #1
S2PL_130719_Blow_Off_6



2013/7/22

CIMG1673 Pic #2
S2PL_130722_Blow_Off_6



CIMG1675 Pic #3
S2PL_130722_CARV-4

2013/7/22



2013/7/22

CIMG1676 Pic #4
S2PL_130722_CARV-2

A photograph of a construction site. In the foreground, there is a dirt path covered with dry grass and small stones. A white hose runs along the path, and a blue pipe is visible in the background. The ground is uneven and appears to be a mix of dirt and gravel. The background shows some greenery and a fence line.

CIMG1677 Pic #5
S2PL_130722_Blow_Off_1

2013/7/22



2013/7/22

CIMG1678 Pic #6
S2PL_130722_Blow_Off_1



2013/7/22

CIMG1681Pic #7
S2PL_130722_Blow_Off_1